




HONDA

R e p l a c e m e n t A/C Compressors



- | |
|--|
| ■ All Sanden TR compressors are 100% new, not re-manufactured |
| ■ Each unit is manufactured on the same line as the Honda original |
| ■ TR replacement compressors come with a one year limited warranty |
| ■ Replacement TR compressors meet or exceed original OEM specs |
| ■ Compressors ship fully charged with original Sanden SP-10 oil |
| ■ Clutch service kits are available to repair worn friction surfaces |

“Original Equipment on Honda Vehicles for Over 15 Years.”

Advanced scroll technology has made Sanden’s TR compressor the scroll compressor of choice by Honda for over 15 years. Scroll compression technology provides superior cooling efficiency and reduced noise vibration harshness. For a smooth, quiet, and comfortable ride, scroll compressors are unmatched in performance. Scroll compressors are extremely difficult to manufacture and even more difficult to re-manufacture. Component parts must be machined to exact tolerances or the compressor will fail prematurely. Don’t settle for imported imitations or re-manufactured compressors. Use only the best...use the original Sanden TR scroll compressor when servicing your A/C system.

HONDA APPLICATION GUIDE

Sanden #	Year	Trim	Eng Type	Liter	Type	Replaces Sanden #
CIVIC						
4914	2005	Si	L4	2.0	TRSA09	4973, 4978, 4980, 4984, 4985
	2005	DX, EX, GX, HX, LX	L4	1.7	TRSA09	4973, 4978, 4980, 4984, 4985
	2004	Si	L4	2.0	TRSA09	4973, 4978, 4980, 4984, 4985
	2004	DX, EX, GX, HX, LX	L4	1.7	TRSA09	4973, 4978, 4980, 4984, 4985
	2003	Si	L4	2.0	TRSA09	4973, 4978, 4980, 4984, 4985
	2003	DX, EX, GX, HX, LX	L4	1.7	TRSA09	4973, 4978, 4980, 4984, 4985
	2002	Si	L4	2.0	TRSA09	4973, 4978, 4980, 4984, 4985
	2002	DX, EX, GX, HX, LX	L4	1.7	TRSA09	4973, 4978, 4980, 4984, 4985
4913	2001	DX, EX, GX, HX, LX	L4	1.7	TRSA09	4968
4993	2000	CX, DX, EX, GX, HX, LX, Si	L4	1.6	TRS090	3057, 3059, 3062, 4955, 4956
	1999	CX, DX, EX, GX, HX, LX, Si	L4	1.6	TRS090	3057, 3059, 3062, 4955, 4956
	1998	CX, DX, EX, GX, HX, LX, Si	L4	1.6	TRS090	3057, 3059, 3062, 4955, 4956
	1997	CX, DX, EX, HX, LX	L4	1.6	TRS090	3057, 3059, 3062, 4955, 4956
	1996	CX, DX, EX, HX, LX	L4	1.6	TRS090	3057, 3059, 3062, 4955, 4956
	1995	CX, DX, LX, VX	L4	1.5	TRS090	3057, 3059, 3062, 4955, 4956
	1995	EX, Si	L4	1.6	TRS090	3057, 3059, 3062, 4955, 4956
	1994	CX, DX, LX, VX	L4	1.5	TRS090	3057, 3059, 3062, 4955, 4956
	1994	EX, Si	L4	1.6	TRS090	3057, 3059, 3062, 4955, 4956
CIVIC DEL SOL						
4993	1995	S	L4	1.5	TRS090	3057, 3059, 3062, 4955, 4956
	1995	Si, VTEC	L4	1.6	TRS090	3057, 3059, 3062, 4955, 4956
	1994	S	L4	1.5	TRS090	3057, 3059, 3062, 4955, 4956
	1994	Si, VTEC	L4	1.6	TRS090	3057, 3059, 3062, 4955, 4956
CR-V						
4993	2001	EX, LX, SE	L4	2.0	TRS090	3057, 3059, 3062, 4955, 4956
	2000	EX, LX, SE	L4	2.0	TRS090	3057, 3059, 3062, 4955, 4956
	1999	EX, LX	L4	2.0	TRS090	3057, 3059, 3062, 4955, 4956
	1998	EX, LX	L4	2.0	TRS090	3057, 3059, 3062, 4955, 4956
	1997	EX, LX	L4	2.0	TRS090	3057, 3059, 3062, 4955, 4956

U.S.
M A D E

Sanden International (USA), Inc. is a registered ISO9001:2002, ISO14001, and TS16949 company.